UNCLASSIFIED

AD NUMBER AD395863 CLASSIFICATION CHANGES TO: UNCLASSIFIED FROM: CONFIDENTIAL LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;
Administrative/Operational Use; 12 NOV 1968.

Other requests shall be referred to Office of the Adjutant General (Army), Washington, DC 20310.

AUTHORITY

AGO ltr 29 Apr 1980 ; AGO ltr 29 Apr 1980

THIS REPORT HAS BEEN DELIMITED AND CLEARED FOR PUBLIC RELEASE UNDER DOD DIRECTIVE 5200.20 AND NO RESTRICTIONS ARE IMPOSED UPON ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

SECURITY MARKING


The classified or limited status of this report applies to each page, unless otherwise marked.

Separate page printouts MUST be marked accordingly.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U.S. Government thereby incurs no responsibility, nor any colligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.



DEPARTMENT OF THE ARMY

OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310

IN REPLY REFER TO

AGAM-P (M) (27 Jan 69) FOR OT UT 684211

31 January 1969

SUBJECT: Operational Report - Lessons Learned, Headquarters, 13th Combat - Aviation (Guardian) Battalion, Period Ending 31 October 1968 (U)

60

SEE DISTRIBUTION

E CU

1. Subject report is forwarded for review and evaluation in accordance with paragraph 5b, AR 525-15. Evaluations and corrective actions should be reported to ACSFOR OT UT, Operational Reports Branch, within 90 days of receipt of covering letter.



- 2. Information contained in this report is provided to insure that the Army realizes current benefits from lessons learned during recent operations.
- 3. To insure that the information provided through the Lessons Learned Program is readily available on a continuous basis, a cumulative Lessons Learned Index containing alphabetical listings of items appearing in the reports is compiled and distributed periodically. Recipients of the attached report are encouraged to recommend items from it for inclusion in the Index by completing and returning the self-addressed form provided at the end of this report.

BY ORDER OF THE SECRETARY OF THE ARMY:

tenneth G. Neickham. KENNETH G. WICKHAM

l Incl

Major General, USA The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Adjutant General School

US Army Air Defense School

US Army Armor School

US Army Artillery and Missile School

US Army Aviation School

Regraded unclassified when separated from classified inclosure.

المريع تا الما

DISTRIBUTION (Cont'd)

- US Army Chemical School
- US Army Civil Affairs School
- US Army Engineer School
- US Army Infantry School
- US Army Intelligence School
- US Army Medical Field Service School
- US Army Military Police School
- US Army Missile and Munitions School
- US Army Ordnance School
- US Army Quartermaster School
- US Army Signal School
- US Army Southeastern Signal School
- US Army Special Warfare School
- US Army Transportation School

Copies furnished:

Office, Chief of Staff, US Army

Deputy Chiefs of Staff

hief of Engineers

Chief of Research and Development

Assistant Chiefs of Staff

Res.arch Analysis Corporation (Library)

OSD(SA), Assistant for Southeast Asia Forces

Director, Weapons Systems Evaluation Group

Defense Documentation Center

Security Officer, Hudson Institute

Commanding Generals

US Army Weapons Command

US Army Flight Training Center

Commanding Officers

Us Army Limited War Laboratory

US Army Logistics, Doctrine Systems & Readiness Agency

US Army Aviation Test Activity

13th Combat Aviation (Guardian) Battalion

DEPARTMENT OF THE ARMY
Headquarters, 13th Combat Aviation (Guardian) Battalion
APO San Francisco 96296

:VBN-G

12 November 1968

SUBJECT: Operational Report of 13th Combat Aviation (Guardian) Battalion for Period Ending 31 October 1968, RCS CSFOR-65(R1) (U)

SEE DISTRIBUTION

- 1. (C) Section 1, Operations: Significant Activities.
 - a. Unit Mission. There was no change to the unit mission during this period.
- b. Organization. At the close of the reporting period the organization of the 13th Combat Aviation (Guardien) Battelion was as follows:
 - (1) Headquarters and Headquarters Detachment
- (2) The 114th Assault Helicopter Comp ny (UH-1) with the 544th Transpertation Detachment (KD) and the 96th Sign 1 Detachment (KL) attached.
- (3) The 121st Assault Helicopter Company (UH-1) with the 80th Transportation Detachment (KD) and the 257th Signal Detachment (KL) attached.
- (4) The 175th Assault Helicopter Company (UH-1) with the 150th Transportation Detachment (KD) and the 28th Signal Detachment (RL) attached.
- (5) The 271st Assault Support Helicopter Company (CH-47) with the 361st Transportation Detachment (KD) attached.
- (6) The 336th Assault Helicopter Company (UH-1) with the 167th Transportation Detachment (KD) and the 277th Signal Detachment (RL) attached.
 - c. Changes in Command and Staff
- (1) LTC Richard A. Keilman, 01932219, was assigned as Commanding Officer on 1 August 1968, LTC James L. Tow, was reassigned to CONUS.
- (2) MAJ William Jugel Jr. 01938874, was assigned as S-2 on 25 September 1968 There was no S-2 assigned at the time Major Jugel assumed the position.
- (3) MAJ Clifford H. Burns, OF100635, was assigned as Assistant S-3 on 10 August 1968. Major Roger K. Pacuette was reassigned to the 121st Assault Helicopter Company.
- (4) MAJ Richard S. Freeze, 087746, was assigned as Battalion Maintenance Officer on 11 August 1963. Major Nicolas P. Stein was reassigned to USAKEUR.
- (5) CPT Max E. Reddick, 02332460, was assigned as Medical Officer on 2 November 1963. Major Gary B. Robnett was Medevaced.

 FORCETOT

 CONFIDENTIAL

 Inclosure 1

 CONFIDENTIAL

 DOD DIR 5200.10

Open association of light contact an intermediate for Period Engine 31 October 1911, red Cartheres with (U) SUBJECT:

- (6) CW3 Marvin C. Albrecht, W3200521, was assigned as administrative saistant on 5 September 1968. ILT David G. Pipes was reassigned to US REUR.
- (7) CH3 James T. Brady Jr., 12201750, was assigned as Personnel Officer on 24 October 1968. C'/3 David W. Nichols was reassigned to CUNUS.
- (8) CW2 Russell E. Johnson, 13431076, was assigned as Motor Maintenance Officer 1 August 1968. C 2 Bernard J. Buons was reassigned to CONUS.
 - (9) CM2 Otis Smith, M3152095, was assigned as Assistant S-4 on 12 August 1968.
 - d. Unit Strength as of 31 October 1968.
 - (1) Military

UNIT	OFFIC	ER.		·:O					TOTAL'	
	Auth	Man	Pres	Auth	Man	Pres	Auth	Pres	Man	Pres
HHD 544th 96th 121st 30th 257th 175th 150th 28th 336th 167th 77th 271st	10 15 1 15 1 15 1 15 1 15 1	17 12 1 12 1 1 12 1 1 12 1 12 1 12 1	13 21 1 22 1 22 1 0 21 1	3 50 1 50 1 0 50 1 0 50 1 0	3 44 1 44 1 0 44 1 0 44 1 0 23	4 37 1 38 1 0 35 1 0 34 1 0	74 149 70 152 72 9 147 72 9 152 72 9	106 120 57 146 48 8 124 70 5 147 45 9	94 216 74 219 74 10 214 74 10 219 74 10	125 178 59 203 50 9 176 72 5 201 47 10
361st 13th C.B	$\frac{1}{100}$	$\frac{1}{86}$	$\frac{1}{104}$	$\frac{1}{233}$	1 207	$\frac{1}{172}$	30 1319	79 1114	82 1557	81 1392

(2) Non-Military

UNIT	DaC <u>Auth</u>	<u>0/H</u>	· VN Aut	h <u>O/H</u>		NATL O/H	CONTRACTOR
HHD	0	0	4	4	0	0	0
114th	0	0	4	14	0	0	0
121st	0	0	25	69	0	0	0
175th	0	0	5	12	0	0	0
336th	0	0	26	53	0	0	0
271st	0	0	0	_13	<u>o</u>	<u>O</u>	<u>0</u>
13th CAB	0	Ō	64	159	Ō	Ù	Ō

- (3) The battalion continues to experience a shortage in the following MOR's.
- (a) 26M2O Air Borne Reder Repairman
- (b) 45J20 Aircraft Armoment Repairmen
- (c) 51M40 Fire-Fighter (d) 67Alf UH-1 Helicopter Repairman

SUBJECT: Operation | Report V/19th Combat Aviation (Guardian) Battalion for Period Enging 31 October 1968, RCS CSFOR-65(R1) (U)

(e) 68B2O Aircraft Turbine Engine Repairman

(f) 68G20 Airframe Reprirman

(g) 71T20 W inten nce Data Specialists

(h) 76T20 Aircraft Repairman Parts Specialists

- (i) 76U2O Communications Electronics Repairm n Parts Speci lists
- (j) 76420 Petroleum Storage Speci lists(k) 76440 Armorer/Unit Supply Specialists
- (1) 67 N4O Maintenance Supervisors (m) 67 N2O Technical Inspectors
- (m) of the resulted mbpectors
- e. Aircraft Status as of 31 October 1968. See Incl 2.
- f. Operational Results as of 31 October 1968. See Incl 3.
- g. Operations. General.
- (1) The 13th Combat aviation (Guardian) Battalion continue to provide aviation assets for pre-planned airmobile assults, troop repositioning and extractions, tactical and administrative resupply, command limison, medical evacuation and direct fire support by armed helicopters in support of the 7th, 9th and 21st ARVN Infantry Divisions and the 44th Special Zone. Support was also provided to Military Advisory Group IV Corps, Special Forces and COADS. The 13th CAB Operations Center continued to function throughout the movement of the headquarters from Can Tho to Sac Trang. This was accomplished by installing the required communications equipment at Soc Trang while the Operations Center at Can Tho continued to contral the battalions aviation assets. At 2400 hours on 24. October 1965 the transition was made to the new Battalion Operations Center at Soc Trang. The new BOC is located in the airfield command bunker which is constructed of steel, cement and earth and will withstand a direct hit by the largest caliber weapon ever utilized by the enemy in an attack on Soc Trang Airfield.
- (2) Airmobile Operations. The b ttalion supported 172 airmobile operations during the period. Two of the more signific nt operations were conducted on 15 and 31 August 1968.
- (a) Intelligence reports received on 14 August indicated that two(2) VC companies and in ammo cache were located along a canal 9-13 Kilometers northeast of hach Soi. The 336th Assault Helicopter Company was notified of the impending operation on the evening of 14 August 1968. Flans were formulated, overlays were made and all supporting elements were notified. Planned directrikes commenced promptly at 0730 and continued until 0900, LZ time. As the strikes progressed, a heavy fire team conducted a visual reconnaissance of the 1 nding zone 10 minutes prior to LZ time. The troop transports departed Rach Soi at 0845 and proceeded to in LZ 15 kilometers northeast of Rach Soi. Three additional lifts were inserted in this LZ. Four hundred more troops were then inserted into an LZ 900 meters NN of the initial LZ. The ground elements then proceeded southwest long both sides of the c nel which was the alleged location of the enemy. An additional ground element had been prepositioned approximately 9 kilometers to the asouthwest of the maneuver clements in a blocking position. A light fire team reconning ahead of the maneuver elements spotted some tents and other equipment and also received sporadic small arms fire. The ground commander decided to insert a recon company to exploit this sighting. The recon company was repositioned twice more during the conduct of this operation to block escape routes as the enemy attempted to avoid the m jor maneuver clements. As the mancuver elements proceeded toward their fin-1 objective they uncovered numerous wearons, armo caches and other assorted equipment. All aviation

AVBN-G

SUBJECT:

Operational Report of 13th Comb t Aviation (Guardian) a tealing for

Period Ending 31 October 1963, RCS CSFOR-65(R1) (U)

assets were released at 1945 hours.

Result of the operation were as follows:

ENEMY FRIENDLY 3 WIA 8 KIA 3 Captured 2 Boxes K-2 ammo Mines 5 Rds 75mm RR ammo 10 Rds 60mm Mort ammo 86 Rds B-40 rocket Russi n Rifles K-1 5 K-2 1 BK 3 MG K-3

The success of this operation was enhanced by the ground commanders capatility of rapidly redeploying his mobile reserve for a through the employment of his aviation assets.

(b) On 28 August 1968, 2 ARVN POW's escaped from a Viet Cong prison comp located approximately 10 kilometers southwest of Vi Thanh. During the afternoon of 30 August the 121st Assault Helicopter Company was assigned the mission of conducting a raid on the camp in support of the 21st ARVN Division. On the evening of 29 August, 12 members of a Provincial Reconnaissance Unit were inserted 3200 meters south of the camp with the mission of infiltrating and acquainting themselves with the lay out of the prison camp so that they would be able to assist in the release and/or defense of the prisoners should the Vo attempt to take their lives before the AkVN's could move in the next morning and free them. At 0635 the next morning a heavy fire team conducted a hasty visual reconnaissance of the LZ just moments before the troop transports inserted 50 troops into the LZ. The troops immediately moved into the prison camp and established a defensive perimeter. As this was being done a Vict Cong force was moving into an assault position 1000 meters north of the camp. As the VC advanced on the comp they encountered devastating fire from the 12 P.U's who had infilteated the previous night. The gunships joined in the attack on the VC and they were repulsed. With this threat chiminated the ARVN's had complete control of the prison camp and the extraction was complete by 0930.

Results of the operation were as follows:

FRIENDLY - Forty-five ARVN POW's were released. Unfortunately, the eight Americ as had been moved to another location on 29 August 1963. There were no friendly casualties.

Ei. 16 KBA

1 VC Suspect

4

NON-G

12 November 1963

SUBJECT Operational Report of 13th Combat Aviation (Guardian) Bettalicn for Period Ending 31 October 1968, RCS CSFOn-65 (U)

2 Rifles
Numerous Medical Supplies
6 - Structures Destroyed

Numerous Documents 4 Sampans Destroyed Camp Destroyed

This operation illustrated again the versatility of an airmobile force in the conduct of a well planned and agressively executed airmobile operation.

- h. Training. The seven VNAF helicopter pilots enrolled in the battalion UH-1D transition training program completed their training on 11 October 1968. The VNAF aviators compiled over 800 hours of flying time as they participated in command and liaison, resupply and combat assault missions. The students were presented their certificates of achievement by the Commanding General of the 1st Aviation Brigade and the Commanding Officer of the 74th VNAF Wing during a graduation ceremony held at Soc Trang Army Airfield on 11 October 1968.
 - i. Morale and Discipline
- (1) The number of approved recommendations for awards received during this period are shown by type and totals awarded:
- DFC 35 SM 1 DS"V" 15 AM"V" 96 ACM"V" 12 BS"S" 18 ACM 27 PH 9 AM 1560
- (2) During this reporting period the number of approved disciplinary actions taken under UMCJ were:

	OFFICER	WARHANT OFFICER	ENLISTED MEN
Gereral	0	0	G
Snedial	0	Õ	3
C 1 1"	0	·)	0
A. 15	0	ı)	33
TA L	<u>ੌ</u>	Ü	36

(3) The following number of personnel were reported as casualties during this period.

KTA 6 1A 18

- (4) Number of personnel that took & & R leave to various countries is denoted below:
- AUS 53 Bnk 35 Haw 95 M.K. 16 M n 10 K.L. 8 Tai 21 Tok 34 VT 15 Punang 3 Sing 3 TOTAL 189.
 - j. Srfety:
 - (1) During the reporting period the Bittalion experienced eight (8)

1/E.J-G

StbJ CT: Operational Report of 1 th Combat Lation (Guard' n) is 'a : Period Indian 31 October 15, 158 U.FuR-65(ml (U)

reportable accidents for a rate of 21.1 decidents per 100 out flying hours. This represents a dicrease of approximately twenty-seven per out from the previous reporting period. Five of these accidents resulted from in the outengine failures, two from loss of anti-torque control, and one was attributed to pilot error.

- (?) The incidence of in-flight engine failures reflected a charge increase over the last reporting period. From 1 August through 31 October 1960, units of the Fattilien experienced a total of fourteen in-flight origine failures. One of these failures was attributed to fereigh object damage, the remaining thirteen failed for internal reasons. Of the thirteen internal failures, twelve were recuised agilies. The average amount of hours flow from time of rebuild to time of failure of these engines was approximately 327 hours.
- k. historical cummary: On to October 1983 the Headquarters and Admiraters Detachment of the 13th Combat aviation B thelion bid a sad forewell to 0 n The, Vertram he coffice 13th Coff since 3 July 1963. The Battalien was ordered to See Tring which is lee ted 41 miles southerst of Can The, and is the here of two sister companies the 356th aHC and the 47th AdC. Movement orders recaired the Detachment to be operational at See Trang net 1 terith in 1 November 1958. The Headquarters Detachment completed the move in three days (24 26 Oct 66). Lest of the property and personnel were cirlifted by CH-47 Helicopters. The move was elimined by read convertible of the organic vehicles in the remaining TO & Equipment. Personnel at the Detachment again demonstrated their ability to perform successful operations a coeffly and professionally. Special command sions are in order for 0 to Hissall Johnson, the Extraction Fotor Maintenance Officer and all the More. Fool Mechanics who worked to the hours in day proporting the Set chaint vehicles for the road convey. The dust mas siteled, the environment in a become familiar; and the men of the 13th CAB are ready to continue to "Get The Job Done"
- (i) Section 2. Lessons Learnee Commander's Chservation, Evaluations and Recommendations.
 - a. Personnel. None.
 - **b.** Operations
 - (1) Insufficient Rigging Equipment.
- (a) Observation. An involving to quantity of righting ecuipment is administed to support it data for conduct of Artificial Loves on IV (e.g.: leptical Zone.
- (t) Evaluation: At the PZ, lack of sufficient rig ing equipment prevents the suprected unit from pre-rigging their loads. Delays are frequently encountered because of the additional regularies to for the supported unit to

AVBN-G 12 November 1968 SUBJECT: Operational Report of 13th Combat Aviation (Guardian) Battalion for Period Ending 31 October 1968, RCS CSFOR-65(R1) (U)

have sufficient work parties and transportation in the PZ to maintain a constant supply of rigied loads. When the PZ and LZ are only a stort distance apart, the problem is magnified due to the short turn-around flight time for each aircraft. The lack of rigging equipment causes the CH-47 to land and remain in the LZ for extended periods of time while the load is de-rigied and the rigging equipment is loaded on the aircraft for backhaul to the PZ. Thus, the LZ size requirement is necessarily larger to accommodate the CH-47 on the ground as well as the other landing aircraft. When utilizing armed escort, the problems of the escort commander are compounded due to the excessive time. The CH-47's are in the LZ.

- (c) Recommendations: Recommend the supported artillery unit be required to obtain and maintain sufficient and proper slings and straps for each Artillery prace and nets for their basic ammo load. Recommend this rigging equipment become a part of their section equipment and that sufficent extra rigging equipment be maintained at the unit headquarters level to support any normal requirement for additional armo resurply. Recommend also that command emphasis at Corps level be placed on the requisitioning and maintenance of the necessary rigging equipment.
 - (2) "Pigov Back" Loads.
- (a) Observations: Seldom do ARVN articlery units utilize the "pigy-back" load, instead artillery pieces are inserted with crews and then supplied with ammo.
- (b) Evaluation: The full capabilities of the CH-47 are not realized until the "piggy-back" load is utilized. The most important advantage of this type load is the capability of putting an artillery piece, crew, and ammo into a firing position at the sare time. Again, the proper rigging equipment must be on hand in order to prepare this type load for transport by CH-47. Fewer sorties will be required to move an artillery battery by utilizing the "piggy-back" method, and at the same time, better utilization of the CH-47 will be realized.
- (c) Recommendation: Recommend the U.S. artillery advisors emphasize to their counterparts, the need for and resultant increase in the efficiency of an artillery move when utilizing the "piggy-back" method.
 - (d) Common frequency for maneuver elements in operational area.
- (a) Observation: Ground units maneuvering in the same operational area do not always operate on or monitor a common FM frequency.
- (b) Evaluation: When maneuver elements are operating on more than one frequency, gunships are not able to continuously monitor all the units in the operational area. Most often this occurs when there are maneuver elements present on the operation who have not been airlifted, but have entered the

AVBN-G

12 hove and 1,6

SUBJECT: Operational Report of 13th Combat Aviation (Guardian Buttarion for Period Ending 31 October 196, RCS CSFOR-65(R1) (U)

operational area by some other mode of transportation. Also the Airmotic Task Force Commander is not able to continuously monitor the progress of the maneuver elements. From the standpoint of placing accurate supporting fines on known or suspected enemy positions, the exact location of all friendly forcer must be known at all times. The use of more than one fremenously the maneuver elements creates a taxa cancereduces the responsiveness of constiput support.

- (c) Recommendation: The Airrobile Task Force Commander should make every effort to have only one PM from ency for the maneuver elements in a given operational area.
 - (4) Air traffic congestion at stagefields/airfields.
- (a) Observation: The near nt significant increase in air traffic density has created here loss operating or dit ons on and around stageficing/airfields.
- (b) Evaluation: To reduce the invarid caused by the increasingly congested conditions at stagefield, a Stagefield Operations (500) is appointed by the unit which furnable the Arr hission Consumder for one tactical operation. The SOC is a captain with extensive background in arrowable operations. The function is to positively control all air may vehicular traffic on and around the stagefield. To accomplish this mission the SOC has control of a late finder detac ment (minus) which is completed to two (2) to nachicles which have the find Fhardio capability. All heard cuarters controlling aviation accounts in the "Delta" are notified daily of the stagefields which are used to control our traffic at stagefields which is not have control owers are been discominated to all aviation units. Occasionally, already so he inguiting as a staging area for taction operations are closed to fixed and matter of hazardous conditions on and around our stagefield. The idea.
- (e) become mations. That the action taken by this has not a telegraph of ficking and a law the hazards of stagefield operations are presented to other axistion units for their consideration.
 - (5) Aurorat Commande. Selection Criteria Observation:
- (a) There has been a definite need to standardize the criteriantilized to select a moraft commanders at the unit level.
- (t) Evaluation: The following g idance was published in the battal, a tactical SOP to standardize the criteria utilized by the units in schooling their aircraft commanders:

AVBN-G

Operational Report of 13th Combat Aviation (Guardian) Battalion for Period of Ending 31 October 1968, NCS CSFOR-65(R1) (U)

- (1) Adminimum of 350 hours flying time in RVM. (Second tour personnel must have logged 100 hours during the 2nd tour.)
 - (2) A minimum of four (4) months in RVF
 - (3) Must be familiar with geographical area.
 - (4) Must have received a border orientation.
- (5) Will be knowledgeable in all slight following procedures and techniques
- (6) Must be capable of performing the duties of trail or lead aircraft of a fortation conducting a combat assault. (Not applicable to Assault Support Helicopter Cornanies).
- (7) Must have demonstrated the ability to remain calm under the stress of combat conditions.
- (ϵ) Exist be thoroughly familiar with aircraft capabilities and limitations.
- (9) Must be capable of recenting a comprehensive operational briefing to his crew, passengers and/or aviators.
- (C) Recommendation: That other aviation headquarters evaluate the criteria as set forth in paramaph (5), (b).
 - c. Training. Mone
 - d. Intelligence. None
 - e. Logistics. None
 - f. Organization. None
 - g. Other. (Maintenance)
- (1) Leaking muster brake cylinders after CF-47 aircraft are deployed by aircraft carrier to RVN
- (a) Observation: Many CB-47 units have had problems with leaking master brake cylinders after treir nineraft were deployed to RVN by aircraft carriers.
- (b) Evaluation: Normally, when the CH-47 is lifted onto the aircraft has been positioned aboard the flight deck. No requirements has been stablished to reset the parking brakes during the movement by ship to RVN.

AVBN-G
SUBJECT: Operational Report of 13th Comba. Avi tion (aurdian) Battalion for Period Ending 31 October 1968, RCS CSFCR-65(R1) (U)

During this move constant pressure on the master brake cylinder causes it to begin leaking. During deployment of the 271st ASHC by ship to RVN, the aircraft cocoons were taken off the rear of the aircraft, the APU started, parking brakes were then reset and the cocoons replaced after the APU cooled down. This procedure was followed once each week during deployment and to date no problems have developed with leaking master brake cylinders.

- (c) Recommendation: Recommend that CH-47 helicopters being deployed to RVN or other areas by aircraft carrier be required to reset the parking brakes at least once each seven days to proclude future problems with the master brake cylinders.
- (2) High Rate of In-flight Engine Failure and Precautionary Landings in UH-1 Aircraft.
- (a) Observation: There has been a high rate of in-flight engine failures and precautionary landings among UH-1B, UH-1C and UH-1D helicopters assigned to this battalion. Engine failures have been particularly high among UH-1B and UH-1C aircraft using rebuilt T53-L11 and T53-L11B engines.
- (h) Evaluation: The UH-1B and UH-1C helicopters assigned to this battalion are all utilized as gunships flying in support of assault helicopter operations. The nature of their mission requires that they fly at high gress weight, high air speed and continually execute maneuvers which place high stress on both the aircraft and the engine. UH-ID helicopters assigned to the battalion have a primary mission as assault helicopters. Their mission requires that they make formation landings into landing zones, often located in rough and difficult termain. Their departure normally employes a maximum power climb to altitude. Engines and airframes of all aircraft are continually subjected to stress approaching design limitations. In an attempt to locate malfunctioning engines prior to in-flight failure, this battalicn has initiated a program wherein pilots, prior to each flight, with the aircraft at a two foot hover, record engine torque, percent N-1, exhaust gas temperature, outside air temperature and gross weights of the aircraft. At the end of each flight the crew chief checks engine coast down time and monitors the engine for unusual néise or excessive smoking. In this manner, several malfunctioning engines have been located and either repaired or removed from service prior to inflight failure. As an additional precaution against engine and airframe failures, this Battalion has initiated a program wherein the companies are required to perform a 100% technical inspection of each aircraft at each second intermediate inspection. This is in addition to the normal requirements in the PMI. During these inspections numerous minor discrepancies h ve been found and corrected which might otherwise have resulted in a precautionary landing, failures or major accidents with resultant loss of life or vital combat aircraft.

al

13 New order 1968 AVBN-GC SUBJECT: Operational Report of 13th Comort Wiation (Constant a Marion for Period Enting 30 October 1968, RGS CSFOR-65(-1) (1)

(c) Recommendation: Recommend that all helicepter compenies experiencing a high rate of in-flight engine failures require pilots we monitor and record vital engine instrument readings and that these recordings be analyzed on a daily basis. In addition, recommend that all helicapter units whose aircraft are subjected to continued stress in the accommandation their daily mission, initiate a program of 100% technical inspection of all aircraft at the second intermediate.

All inclosures 3 Incl- w/d, Hq, DA

1. Organization and Stationing 2. 13th CAB Aircraft Status

3. 13th CAB Operational Statistics

he pass of terfinan

110,03 Commanding

DISTRIBUTION

2 - CINCUSARPAC

3 - CG, USARV

2 - CG, 1st Aviation Brigade

4 -- CO, 164th Aviation Greup

8 - S-3 Operational File

AVGN (12 Nov 68) lst T-1

SUFJECT: Operational Report of the 13th October 1968, RCS CSFOR-65 (R1) (U)

DA, HO, 164TH AVIATION GROUP, APO 96215 30 November 1968

SEE DISTRIBUTION

- 1. (U) The attached 13th CAF ORLL for the period ending 31 October 1968 has been evaluated by this headquarters as required by USARV. . Reg 525-15.
- 2. (U) The authorized unit strength for HHD, 13th CAE and authorized civilian strength for 13th CAE are listed below:
 - a. MILITARY HHD, 13th CAE

 OFF
 WO
 E1
 TOTAL

 22
 2
 85
 109

b. CIVILIAM 13th CAE

HHD	11Lth AHC	121 st AHC	175th AHC	376th. AHC	271st ASHC	TOTAL
2	5	18	5	15	2	47

- 3. (C) Section 2, Lessons Learned: Commander's Observations, Evaluations, and Recommendations.
- a. Insufficient Rigging Equipment; Concur with the recommendation. IV Corps advisors are attempting to produce the required rigging equipment for the ARVN units.
- b. "Piggy Back" Loads: U.S. Advisors and their counterparts are aware of "Piggy Back" load advantages and disadvantages. This method of transport is not being employed due to the shortage of rigging equipment. The required equipment is expected to be available soon and this method of rigging will be frequently employed.
- c. Common frequency for maneuver elements: Non Concur with the recommendation. One FM frequency for all ground maneuver units would seriously restrict ground commanders in the control of their units. All ground elements on a common frequenc, with the gunships is not desirable. The present method of air to ground coordination for close fire support is desirable and adequate.

AVGN (12 Nov 68) 1st Ind 30 November 1968 SUBJECT: Operational Report of the 13th 'call the lation (Guardian) Battalion f the Pariod ending 51 0 60 r 1068, RCS CSFOR-5 (RI) (J)

- d. Air traffic congestion at stagefields/airfields: Hethods of controlling aircraft at tactical stagefields as contained in the evaluation are submitted for consideration only. Specific measures for stagefield air traffic control must be based on the tactical situation, availability of equipment and the availability of personnel. Control frequencies for uncontrolled airfields are listed in the Tactical Aerodrome Directory for Vietnam.
- e. Aircraft Commander Selection Criteria Observation: The minimum criteria for selection and designation of aircraft commanders as stated in 1st Aviation Prigade Regulation '5-6, dated 1 November 1968, is considered adequate by this headquarters.
 - f. Leaking master brake cylinders on CH-47 aircraft:
- (1) The first sentence in the evaluation should read "The parking brakes are set when CM-47 aircraft are positioned on the carrier flight deck, with no requirement to reset the brakes during surface movement."
- (2) The recommendation to reset the helicopter parking brakes weekly should be evaluated to determine its merit.
- g. High rate of inflight engine failure and precautionary landings in UH-l aircraft: The action stated in the evaluation and recommendation has been successful for the 13th CAB. To allow ample time for the performance of scheduled maintenance, each aircraft is allocated a 24 hour stand down maintenance period for the intermediate inspection. This stand down period provides ample time for a thorough technical inspection and correction of deficiencies.

4.(U)The 13th Combat Aviation Battalion has accomplished all assigned missions during this reporting period.

LEO C. ERYAN

Acting Commander

DISTRIBUTION:

2 DA, ATTN: ACSFOR

1 CG, 1st Avn Bde, ATTN: AVBA-C

5 CO, 13th CAB 2 S3, 164th CAG

AVBA-C (12 Nov 68) 2d Ind SUBJECT: Operational Report of 13th Combat Aviation (Guardian) Battalion for Period Ending 31 October 1968, RC5 CSFOR-65 (R1) (U)

DA, HEADQUARTERS, 1ST AVIATION BEIGADE, APO 96384 11)EC !...

THEU: Commanding General, United States Army Vietnam, ATTN: AVHGC-DST, APO 96375

Commander-in-Chief, United States Army Pacific, ATTN: GPCF-CT, APO 96558

10: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C., 20310

- 1. (U) This headquarters has reviewed this report, considers it to be adequate, and concurs with the contents as indorsed.
- 2. (C) The following additional comments are considered pertinent:
- a. Paragraph 2b(1), page 6. In accordance with paragraph 1-3, a, TM 55-450-11, the transported unit is responsible to furnish slings, straps, cord, clevises, pauding, tape, etc., used in rigging the equipment to be transported. USANV G-4 has established a liberal BCI for sling equipment authorized to be on hand at the supported unit level. This BOI will be published as a 725 series USARV Regulation in the near future.

b. Paragraph 2g(2), page 9. This headquarters submitted a letter to USAtV on 16 Nov 68 expressing concern in this area. Correct statistics show that fifty seven rebuilt engines were lost during the four month period, July - October. The average time per engine was 374.02 hours. It was recommended that this matter be pursued to determine the overall impact of ANADMAC rebuilt engines within USARV. It is not considered essential to perform a 100% technical inspection during the second intermediate. Normal inspections, conducted as required, are considered adequate to cetect minor discrepancies.

FOR THE COMMANDER:

5. PETERSON

ILT, AGC

ASST ADJ GEN

Lee I Letour

AVHGC-DST (12 Nov 68) 3d Ind

SUBJECT: Operational Report of 13th Combat Aviation (Guardian) Battalion for Period Ending 31 October 1968, RCS CSFOR-65(11) (U)

TO: Commander in Chief, United States Army, Pacific, ATTN: GFOP-LT, APO 96558

1. This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 31 October 1968 from Headquarters, 13th Combat Aviation Battalion.

2. Comments follow:

- a. Reference item concerning air traffic congestion at stagefields/airfields, page 8, paragraph 2b(4). Concur. This headquarters has recently required subordinate commands to make a specific officer responsible for each airfield used by US Army Forces. MACV Directive 95-7 requires that an airfield commander/coordinator be appointed for forward airstrips.
- b. Reference item concerning leaking master brake cylinders after CH-47 aircraft are deployed by carrier to RVN, page 9, paragraph 2g(1). Concur. In view of the success of procedures used by the 271st ASHC, concur with the recommendation, however, shipboard safety must be considered.
- c. Reference item concerning high rate of inflight engine failure and precautionary landings in UH-1 aircraft, page 10, paragraph 2g(2) and 2d Indorsement, paragraph 2b. Concur. It is the unit maintenance officer's prerogative to increase the frequency of inspections to fit hazardous operating conditions. AVS COM has been made aware of this problem.

FOR THE COMMANDER:

W. C. ARNTZ CPT, AGC

Assistant Adjutant) General

Cy furn: HQ 1st Avn Bde HQ 13th CAB GPOP-DT (12 Nov 68) 4th Ind (U)
SUBJECT: Operational Report of HQ, 13th Cbt Avn (Guardian) Bn for
Period Ending 31 October 1968, RCS CSFOR-65 (R1)

HQ, US Army, Pacific, APO San Francisco 96558 8 JAN 1965

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. $20310\,$

This headquarters has evaluated subject report and forwarding indorsements and concurs in the report as indorsed.

FOR THE COMMANDER IN CHIEF:

16

DOCUMENT CONT		
(Security classification of tills, body of abstract and indexing a 1. ORIGINATING ACTIVITY (Corporate author)	unclation must be entered when the overall report is classified:	-
	CONFIDENTIAL	1
HQ, OACSFOR, DA, Washington, D.C. 20310	2b. GROUP	1
3. REPORT TITLE	14	-
Battalion, Period Ending 31 October	d, Hq, 13th Combat Aviation (Ganciene) 1968 (U)	-
4. DESCRIPTIVE NOTES (Type of report and inclusive dates)	70000 000004-0- 1 Aug - 31 Uc 1958	Į
Experiences of unit engaged in counterinsu	rgency operations, I Adg 31 A 17 A	-
CO, 13th Combat Aviation (Guardian)	Battalion	The state of the s
J. REPORT DATE	78, TOTAL NO. OF PAGES 76. NO. OF BEES	- <u>į</u>
12 Nov 1968	19	Í
84, CONTRACT OR GRANT NO.	M. ORIGINATOR'S REPORT NUMBERIS)	1
b, PROJECT NO.	684211	1
		1
e. N/A	90. OTHER REPORT NO.(3) (Any other matter, and in the montgried this report)	i
	*	1
10 DISTRIBUTION STATEMENT		-1
14. SUPPLEMENTARY NOTES	12. SPONSORING MILITARY ACTIVITY	
N/A	OACSFOR, DA, Washington, D.C. 20310	,
IN ABSTRACT	Section 4 parameters to 10 percent determine to 10 per	
		1
		í
	•	,
		1
		1
		}
		3
,		-
T de la companya de l		1
	•	-
		-
	•	
	17	1
DD FORM 1473	UNGLASSIFIED	

Security Classification

The following items are recommended for inclusion in the Lessons Learned Index: ITEM 1 * SUBJECT TITLE ** FOR OT UT # ***PAGE # ITEM 2 SUBJECT TITLE FOR OT UT # PAGE # ITEM 3 SUBJECT TITLE FOR OT UT # PAGE :: ITEM 4 SUBJECT TITLE FOR OT UT # PAGE # ITEM 5 SUBJECT TITLE FOR OT UT # of interest.

* Subject Title: A short (one sentence or phrase) description of the item

** FOR OT UT # : Appears in the Reply Reference line of the Letter of Transmittal. This number must be accurately stated.

***Page # : That page on which the item of interest is located.

- - FOLD - - .

DEPARTMENT OF THE ARMY

DEPARTMENT OF THE ARMY

OFFICIAL BUSINESS

Office of the Assistant Chief of Staff for Force Development
ATTN: Operational Reports Branch Headquarters, Department of the Army Washington, D.C. 20310

DA Label 18, 1 APR 59 PREVIOUS EDITIONS OF THIS LABEL ARE OBSOLETE.

- - FOLD - - -

TAPLE